SURFACE INSPECTION COMPLIANCE REPORT

Date of Inspection: 9 July 1992
Case Serial No.: <u>UT-056-07P, UT-056-07-A, UT-056-07-B</u>
Operator: Jumbo Mining
Project Description: Cyanide Heap Leach Mining
Legal Description: <u>T. 14 and 15 S., R. 10 and 11 W., Sec. 35,</u> 36, 6, 7, 8, 1
District and Resource Area: Richfield/House Range
Inspector: Christina Reid, Rody Cox

REPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)

On July 9, 1992, Rody and I stopped at Jumbo Mining to perform a brief inspection. We first visited the site of the proposed Mizpah Pit. The drill roads we inspected seem to be revegetating themselves but they are not recontoured. Most of the older drill holes we found were plugged with cement. The cuttings are still piled on the surface. The two holes we found tags for are the JW 92-1 and MZ 81-23. The '92 hole was not plugged. Due to the lateness of the day, we decided that another inspection would need to be scheduled for another full day.

The gate to the main mine was locked. We continued to inspect the site on foot. The two most disturbing sites were the ponds and the area with sodium cyanide barrels and open lime bags. The ponds contained water and the exposed liners were torn in several places. The cyanide drums and open lime bags were north of the ponds approximately 100 feet.

We walked to the trailers and visited with Jim Bettridge. He told us that David Hartshorn was gone for the day. The operation is still in non-active status. Mr. Bettridge was concerned about upgrading a road to Jumbo's phone station/receiver. Rody told him that an amendment to Jumbo's Plan or Notice would need to be filed 15 days prior to their work on the road. There are no unforeseen problems with this proposed work.

Mr. Bettridge assured us that there was no cyanide in the ponds. They are not covered or fenced. Pictures were taken of the ponds and drums. A more detailed inspection will be scheduled with Mr. Hartshorn in the future.